GEORGE DEUKMEJIAN, Governor



714/744 P STREET SACRAMENTO, CA 95814



Preliminary Assessment Summary

Valerion Corporation 2180 Iowa Avenue Riverside, CA 92507

Preparer: Michael Pardee
Toxic Substances Control Division
Southern California Section
(213) 620-4469

June 1984

Problem and History:

Valerion Corporation (now GTE-Valerion) manufactured tungsten carbide toolings from 1970 until October 1982 at 2180 Iowa Avenue in Riverside, CA. Wastes included metal filings, heptane (solvent) used in milling, grinding sludge, oil and graphite. The metal filings were reclaimed and returned to the production process. The heptane was recycled through an evaporative distillation process that was 97.85% efficient, the 2.15% left over was lost to the atmosphere due to evaporation. The grinding sludge was collected in 55 gallon drums, allowed to dry out and reused in production.

Riverside Public Works and the RWQCB inspected the site in 1978 and 1980, respectively, and found no problems. In January 1981, a complaint filed at Riverside Fire Dept. reported illegal dumping of oil and graphite on-site. A company official confirmed that the dumping had occurred, but indicated such disposal methods were no longer employed. A follow-up inspection by Industrial Waste Staff found trace materials of an oil origin in two areas.

Recommendation

Oily wastes were illegally disposed on-site for an unspecified period of time. Site inspections have been conducted. However, no samples were taken. Low priority status for soil analysis is recommended.

PRELIMINARY ASSESSMENT Region 9 Michael Pardee (213) 620-4469

Preparer's Name Michael Pardee (213) 620-4469

Date June 1984

		3) 620=4469	
		SOURCE	INFORMATION
1.	Site ID Number		CAD 980884415
2.	Site Name	swis .	Valerion Corporation
3.	Site Location	Drive-by 6/25/84	2180 Iowa Avenue Riverside, CA 92507
4.	County	Drive-by 6/25/84	Riverside
5.	Owner (Address & telephone no.)	Phone contact Ed Santimaw GTE-Valerion (714) 781-4382 6/26/84	GTE - Valerion Corporation 750 Stephensen Hwy Troy, Michigan 48007-3950 (313) 589-1000
6.	Operator (Address & telephone no.)	Phone contact Ed Santimaw GTE- Valerion (714) 781-4382 6/26/84	Valerion Corporation 2180 Iowa Avenue Riverside, CA 92507 (714) 784-0661
7.	Type of Ownership (7	Ed Santimaw 4) 781-4382 6/26/8	Private
8.	Status (7	Ed Santimaw 4) 781-4382 6/26/8	Inactive - for sale
9.	Source Activity	Phone contact Ed Santimaw GTE-Valerion (714) 781-4382 6/26/84	Manufacture tungsten carbide tooling.
10.	Years of Operation (7	Ed Santimaw 4) 781-4382 6/26/84	1970 - 1982
11.	Facility Type	City of Riverside Interoffice Memo 1/15/81	55 gallon drums Illegal dumping of oil in 2 areas
12.	Waste Type and Description	Phone contact Ed Santimaw GTE-Valerion (714) 781-4382 6/26/84 City of Riverside Interoffice Memo	Metal filing Heptane (solvent) Grinding sludge Oil Graphite

13. G	ontacts Carl MacPetrie, GTE-Valerion Corporation (313) 589-1000 Ed Santimaw, GTE-Valerion Corporation (313) 589-1000 Jim Herman, GTE-Valerion Corporation (714) 784-0661 Wayne Fugato, Columbia-O'Gorman Co. (714) 781-4382 See Agency Contact Record.
14. I	ncidents None documented.
F	ire and Explosion Direct Contact
10 <i>/</i>	nspections (date, type, by whom, recommendations) (6, 10, 17/78 - Riverside Industrial Waste. Source Control Monitoring inspection No problem. (21/80 - General inspection, RWQCB. No problems evident. (3/81 - General inspection, Riverside Public Works. Traces of oil and graphite present in 2 areas. No problem as only residue.
	•
	nforcement History (list date, type of action, requirements, utcome)
	None documented.
O T a	Initial recommendation for further action: ily wastes were illegally disposed on-site for an unspecified period of time. he site has been inspected but not sampled. Low priority status for soil nalysis is recommended. EPA recommendation for further action: Sul Alwall memo
	esponse Termination: No Further Action Pending X_ Active ustification: In pite disposal of hazardous waste warrant the inspection at this facility. [1] [1] [2] [3]

PRELIMINARY ASSESSMENT REVIEW

VALERION CORPORATION 2180 Iowa Avenue Riverside, CA

DISCUSSION

The PA preparer indicates that "oily wastes were illegally disposed on-site for an unspecified period of time. Site inspections have been conducted. However, no samples were taken. Low priority status for soil analysis is recommended." The PA references a follow-up site inspection by Industrial Waste staff found "trace materials of an oil origin in two areas".

RECOMMENDATION

I do not believe that there is sufficient evidence in the PA to support a recommendation of a low-priority for site work; rather, there is sufficient reason to elevate the priority for a site inspection and collection of soil samples from a low priority to a medium to medium-high priority.

Thomas A. Mix

Superfund Programs Branch

February 15, 1985

		SOURCE	INFORMATION
19.	Observed Release		
20.	Depth to Aquifer		
21.	Net Precipitation Net seas. rainfall Evaporation		
22.	Permeability of Unsaturated Zone		
23.	Physical State		
24.	Containment (Ground Water) '		·
25.	Toxicity		
26.	Persistence		
27.	Waste Quantity		
28.	Ground Water Use		
29.	Distance to Well		
3C.	Population Served (by Ground Water)		-

	SOURCE	INFORMATION
31. Facility Slope		
32. l yr. 24 hr. rainfall		
33. Distance to Surface Water		
34. Containment (Surface Water)	٠	
35. Surface Water Use		
36. Distance to Sensi- tive Environment		
37. Population Served (by Surface Water)		
38. Distance to Water Intake		
39. Reactivity		
40. Incompatibility		
41. Toxicity (Air)		,
42. Population within 4 mile radius	·	
43. Land Use		

MEMO OF CALL

Name: _	Ed Santiman Date: 6/26/64
Firm: _	GTE-Valeum Time: 1:35P.M.
	750 Stephenson 1+WY Person Taking or Making Call: M. Pardee:
	Truy Michigan 48007-3950
•	•
Telephon	e No.: <u>(313 589 - 1</u> 000
Subject: .	Valeron-Corporation 2180 IOWA are Russido
Message:	The plant produced tungetin Carlide tooling.
	Wastes included metal filings, Heptaro solvent used
	in milling and grinding sludge.
	The metal filings were reclaimed and returned
	to the production pricess. The heptano solvent
 	was recycled through a evaporative distallation
	ruces that was 97.85% efficient, the 2,15%
	lext was lost to the atmosphere from evaporation
	The grinding sludge was collected in 55 sollon
	drums, allowed to enraporate and recycled beach
	into production. No master une ener disposes
	of m-site.
	according to both sentlemen a disgrundles
	employee mas inprêt became he got fired. He
	called many ajencies accusing the Plant of illegal
	disposal practices. No evidence was ever ablaving
	ever proving the allegation.
· · · · · · · · · · · · · · · · · · ·	currently the plant is for sale and it is
	oursel by GTE-Valeron 750 Stephensen HWY,
	truy, Mich 48007-3950.
1 76	Mo incident of any kind ever occured on the site. The plant operate flow 1980 until Oct 1982.


MEMO OF CALL

Name:	Jim Herman	Date:6/26/84
Firm:	Jaleron Corp	Time:
	12391: Sampon	Person Taking or Making Call: Muchael Pardle
	Ruersido, la 92503	
		 •
Telephone	No.: (714) 784-0661	
Subject:	Valenite Plant 2180	DIOWA aux Ruersico
Message: _	Mr. Herman state	id he is the local contact
	for the plant. He	said the Plant closed in
	,	leron Corp merged with
		It used to produce Carbido
	inserts son metal	cutting & removal. He
		as a Chemica O used in the
_	•	es stored in 55 gallon
		all of the chums were
	claned out when	
	He had no i	information on despesal
	pranties: He sais	I I should call the ald
		Detruit, mich (3/3) 589-1000
		ation (Ed Santiman)
***************************************	7	
		•

	N. 44 T. N.	<u> </u>
		

MEMO OF CALL

Name: _	Wayne Fugato	Date: 6(26(84
	Columbia - O Gorman Co	Time: 1:00 p.m.
	3638 University are	Person Taking or Making Call: M. Pardel .
	Ruersido, Ca 92501	
		•
Telephon	e No.: (714) 781-4382	: :
Subject: .	Valente Plant 31	80 TOWA and Ruerrido
Message:	Mr. Fugato compin	red that the Valerin
	. ,	50, Troy Muchepay curs
	the plant and the le	end it sits on. He said
	· · · · · · · · · · · · · · · · · · ·	m 1968 or 69 until 1983.
	That is all the infor	
	/	
•		
		ı
		•
		
		•



Name: V	elonito.	Valerin	Corp		т.в	
Address:	2180 Ic	WA am)		SIC.#_	
City, Zip:	Ruers	do Ca	9250	7		
			SITE DR	IVE-BY		
1. Štatus	a.	Active Inactive	() b	. Different	Company	
2. Setting	g a.	Urban Suburban Rural	() b	Residentia Commercial Industrial Other	. (4)	Near: RR tracks (Drainage (Freeway (Other
3. Waste	а.	Group 1 (Group 2 (Group 3 ()	• Liquid (Sludge (Solid (Other)	Undetermined () None Visible (X)
4. Waste Contair		Pond () Sump () Pit ()	b	 Drum/Brl Pail/Can Trash can Dumpster Box/Pallet 	() c. () () ()	To: Ground () Paving () Drain () Other
	d.	Piled Scattered	()	Bag/Sack Vehicle		Tanks () Other
5. Miscel	laneous a.	Odors	none		b. Vegeta	ation Citrus Groves
	ċ c.	Topography	flat	<u></u>	d. Site (Dbservability (o co
6. Map & Comment						
		•			•	re grounds are
well hept						
disposal u	vas vusi	66. h	s ton	hs, drum	of cont	ames well
misible,	701 Sale	sign -	olu G	mbra - 0 114) 781-	Gorman 4382	Co
7. Evalua	tion a.	No Problem		14) 78(- b. SAP FO	ollow-up ():
	c.	Possible A	bandoned ()	d. Refer	cal to ()	
(Rev. 2/84	>	2160	` '	Date: (12/14 Licharl Pe	wdee